BumperSign Solar

INSTALLATION INSTRUCTIONS







Tools Required



Chalk

Wire Brush



Mallet





Vacuum



Tape Measure



Phillips bit

Level





Rotary Hammer Drill with 1" Carbide Bit



Epoxy Gun



Allen Keys

6´-Step Ladder




McCue Corporation Peabody, Massachusetts, USA +1 (800) 800 8503


McCue UK & Europe Milton Keynes, United Kingdom +44 (0)1908 365 511 <u>uksales@mccue.com</u>


McCue Asia 迈客(厦门)有限公司 Xiamen, Fujian, China +86-592-2200790 mccue.com





















Slide the 4 Clip-On Nuts into place over the mounting holes on the Solar Panel.




Drop the Solar Panel Cable through the Center hole of the Panel Bracket and secure the panel to the bracket using 4 M5 screws.






Position the Solar Panel Assembly on the top over the cover so that the solar panel is facing South and secure using 4 10-32 screws.









Plug the Solar Panel into the Socket on the top of the cover.

